




Right: View southwesterly at the North landing of the Phase II 5<sup>th</sup> Street bridge; "found" granite blocks, steps down to Fielding East ball field.





Above: westerly view of new Phase II 5<sup>th</sup> Street footbridge. Soils are much better than Phase I, and plants are growing much better.



Above: Looking northerly from the end of 5<sup>th</sup> Street: South landing of the new Phase II footbridge, University Village Step II in the background.

Below: Looking easterly to 6<sup>th</sup> Street from 5<sup>th</sup> Street, south side of creek.

