


Head



Sill

817 Ramona--Typical Window Details